

14000Z  
**ENVIRONMETRICS**

2345 Millpark Drive  
Maryland Heights, MO 63043-3529  
(314) 427-0550

## FACSIMILE TRANSMISSION

TO: Ken Braig

FROM: Anne Morris

TOTAL PAGES (including cover page): 4

COMMENTS:

---

---

---

---

---

Should you have any problems with this transmission,  
Please call:

**ENVIRONMETRICS, INC.**

(314) 427-7306  
fax

# ENVIRONMETRICS

2345 Millpark Drive  
Maryland Heights, MO 63043-3529  
(314) 427-0550

July 28, 1995

Riedel Environmental Services  
500 Eastern Ave.  
BENSONVILLE, IL. 60106

Attn: Ken Braig

Enclosed you will find analytical reports for the samples described below:

Date Received: 07/19/95  
Chain of Custody Number: 1948-RE  
Environmetrics Laboratory Number: 9507/245

I have reviewed the data generated by the laboratory and have found the data to conform to the applicable methods and QC criteria. If you have any questions, please feel free to call me at (314) 427-0550.

Sincerely,

Anne Morris

Anne Morris  
Project Manager

Enclosure: Invoice Number 33031

# ENVIRONMETRICS

RIEDEL ENVIRONMENTAL SERVICES  
500 EASTERN AVENUE  
BENSONVILLE, IL 60106

2345 Millpark Drive  
Maryland Heights, MO 63043-3529  
(314) 427-0550

ATTN: MARK DOUGLAS

INVOICE # 33031  
PROJECT # 8168 SAUGET SITE G

## SEMIVOLATILE ORGANIC COMPOUNDS METHOD SW-846 8270

SAMPLE ID: METHOD BLANK  
LAB ID: WASBLK6572

<u>CAS NUMBER</u>		<u>PRACTICAL QUANTITATION</u>	<u>RESULTS</u>
		<u>LIMIT</u>	
120-83-2	2,4-Dichlorophenol	10 µg/l	U µg/l
88-74-4	2-Nitroaniline	50	U
84-66-2	Diethylphthalate	10	U

U = UNDETECTED  
B = PRESENT IN BLANK  
J = DETECTED, BUT BELOW PRACTICAL  
QUANTITATION LIMIT  
DATE COLLECTED : ---  
DATE RECEIVED : ---  
DATE EXTRACTED : 7/20/95  
DATE ANALYZED : 7/24/95  
ANALYST : D.C.

# ENVIRONMETRICS

RIEDEL ENVIRONMENTAL SERVICES  
500 EASTERN AVENUE  
BENSONVILLE, IL 60106

2345 Millpark Drive  
Maryland Heights, MO 63043-3529  
(314) 427-0550

ATTN: MARK DOUGLAS

INVOICE # 33031  
PROJECT # 8168 SAUGET SITE G

## SEMIVOLATILE ORGANIC COMPOUNDS METHOD SW-846 8270

SAMPLE ID: SW-JULY  
LAB ID: 9507/245-001

<u>CAS NUMBER</u>		<u>PRACTICAL QUANTITATION</u>	<u>RESULTS</u>
		<u>LIMIT</u>	
120-83-2	2,4-Dichlorophenol	12 µg/l	U µg/l
88-74-4	2-Nitroaniline	58	U
84-66-2	Diethylphthalate	12	U

U = UNDETECTED  
B = PRESENT IN BLANK  
J = DETECTED, BUT BELOW PRACTICAL  
QUANTITATION LIMIT  
DATE COLLECTED : 7/18/95 14:30  
DATE RECEIVED : 7/19/95 11:45  
DATE EXTRACTED : 7/20/95  
DATE ANALYZED : 7/24/95  
ANALYST : D.C.

**ENVIRONMETRICS**

2345 Millpark Drive  
Maryland Heights, MO 63043-3529  
(314) 427-0550

RIEDEL ENVIRONMENTAL SERVICES  
500 EASTERN AVENUE  
BENSONVILLE, IL 60106

ATTN: MARK DOUGLAS

INVOICE # 32908  
PROJECT # 8168, SAUGET SITE G

**PESTICIDES & PCB ANALYSIS**  
**METHOD EPA 608**

SAMPLE ID: SW-JULY  
LAB ID: 9507/152-003

<u>CAS#</u>	<u>PARAMETER</u>	<u>PRACTICAL QUANTITATION LIMIT</u>	<u>RESULTS</u>
12674-11-2	PCB-1016	1.00 µg/l	U µg/l
1104-28-2	PCB-1221	2.00	U
11141-16-5	PCB-1232	1.00	U
53469-21-9	PCB-1242	1.00	U
12672-29-6	PCB-1248	1.00	U
11097-69-1	PCB-1254	1.00	U
11096-82-5	PCB 1260	1.00	U

U = UNDETECTED  
B = PRESENT IN BLANK  
J = DETECTED, BUT BELOW PRACTICAL  
QUANTITATION LIMIT  
DATE COLLECTED : 7/12/95 15:00  
DATE RECEIVED : 7/12/95 17:02  
DATE ANALYZED : 7/18/95  
ANALYST : J.K.